

# ***THE PINSKE EDGE***

## **#113125 11” Indexing Arms**

The 11” Indexing Arms are preset for use with the Wavy Base and Bit to remove 1/16” of material from each side of the seam.

No measuring – just set the Indexing Arms over the Straight Edge and move the Straight Edge back until the Indexing Arms are tight. Clamp the Straight Edge down and remove the Indexing Arms. The Straight Edge is backset to remove 1/16” for your wavy seam.

The Pinske Edge  
119 Main Street, P.O. Box 68  
Plato, MN 55370 USA  
Fax – 320-238-2385 - Phone 320-238-2196 or 1-800-TPINSKE  
[www.pinske-edge.com](http://www.pinske-edge.com) – [info@pinske-edge.com](mailto:info@pinske-edge.com)